Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: BANKS SWD 1

Field Name: BANKS Well File #: 90230

Date Incident:1/11/2014Time Incident:1100Facility ID Number:County:MCKENZIETwp: 153Rng: 97Sec: 30Qtr:

Location Description:

Submitted By: Mike McMillian Received By:

Contact Person: Wade Bragg

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 5 Miles **Distance Nearest Water Well:** 5 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Unknown Spilled Units Recovered Units Followup Units

	Opiniou	• • • • • • • • • • • • • • • • • • • •	7100070704	•	
Oil	0	barrels	0	barrels	
Brine	2	barrels	2	barrels	
Other	0	barrels	0	barrels	

Description of Other Released Contaminant:

N/A

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None ... Liner contained all brine

Areal Extent:

N/A

Potential Environmental Impacts:

None ... Liner contained all brine

Action Taken or Planned:

Spill was contained on location in an area approx 20x20. Hydro Excavating was preformed to vacuum up free standing liquid and contaminated soil.

Wastes Disposal Location: PDI Prairie Disposal Inc.

Agencies Involved:

Updates

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping leak on location, remained on location, according to the report. NDIC retains oversight.